

# 5 Tips for a Successful Factory Acceptance Test (FAT)



**FRAIN INTEGRATION**

At Frain, every project, machine or complete line of equipment is thoroughly inspected and put through an FAT before it leaves our building.

1



## **Come Prepared and In Person**

It is important to see your machine running in person with your product, and validate 100% your specifications and operational efficiencies.

2



## **Bring the Right People**

Involve individuals that will install, operate, maintain, and others involved with the machine for start up support and training.

3



## **Plan for a Full Day**

Fine tune and ensure your operation runs smoothly and nuances are addressed prior to installation for a successful transition.

4



## **Ask Questions**

Review your specifications and ask questions to get your machine to run the way you want it.

5



## **Move Ahead with Confidence**

Protect your investment with a 2-week right of return and a 6-month warranty on all replacement parts.